

## TRACK INSPECTION REPORT

Name WALTER BRYANT Date 08-09-16 Page 1 of 2  
(Please Print)

## Watchman

WO# 2516460

Inspected From Cold Springs

To Camden

[illegible]**Item**

## Comments

Riding Inspection - Track inspection Completed  
No defect's noted.

**Were switches in the area inspected?**

**Yes** \_\_\_\_\_

No ☒

**Is this a Special Inspection?**

Yes \_\_\_\_\_

No ☒

Reason for Special Inspection?

Walter W. B. G. t  
Track Inspectors Signature

*James Reave*  
Supervisory Certification

8/10/16  
Date

## TRACK INSPECTION REPORT

Name W. Bryant Date 08-09-16 Page 2 of 2  
(Please Print)

## Watchman

WO# 2516460

Inspected From DEMM To LIME

[illegible]**Item**

## Comments

Riding Inspection - Track inspection completed

Were switches in the area inspected? Yes \_\_\_\_\_ No ✓

Is this a Special Inspection? Yes \_\_\_\_\_ No ✓

Reason for Special Inspection?

Walter W. Ryan  
Track Inspectors Signature

*Jane Rasmussen*  
Supervisory Certification

8/10/16  
Date



## Maryland Department of Transportation

### Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2515816 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

1) Track inspection completed..No defects noted..

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
---------	-------------	-----------------	-------------------	--------------

CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/11/16
Target Finish:	8/11/16
Actual Start:	8/10/16
Actual Finish:	8/10/16
Report Date:	8/6/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-#####- #####-####-####- #####-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		



Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2515816 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

1) Track inspection completed..No defects noted..

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure



- Maximo

Maryland Department of Transportation

## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2515816 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

1) Track inspection completed..No defects noted..

### Related Records

WO	Description	Class	Status	Relationship
3339551	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

### Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	LEAD		WBRYAN						N		08:00	00:00	224.24
Total Actual Labor:													224.24



- Maximo

Maryland Department of Transportation

## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2515816 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

1) Track inspection completed..No defects noted..

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor



## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 3339551 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)

1) Track inspection completed..No defects noted..

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:		License:	
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
---------	-------------	-----------------	-------------------	--------------

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/22/18
Reported By:	TSVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

### Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		



Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 3339551 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)

1) Track inspection completed..No defects noted..

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure





- Maximo

Maryland Department of Transportation

## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 3339551 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)

1) Track inspection completed..No defects noted..

### Related Records

WO	Description	Class	Status	Relationship
2515816	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

# TRACK INSPECTION REPORT

Name W. BRYANT Date 6-8-10-16 Page 1 of 2  
(Please Print)

Watchman \_\_\_\_\_ WO # 2515816

Inspected From Linthicum To Cromwell

[illegible]

Item	Comments
------	----------

[illegible]

Were switches in the area inspected? Yes ✓ No       

Is this a Special Inspection? Yes \_\_\_\_\_ No ✓

Reason for Special Inspection?

Walter W. B. Gant  
Track Inspectors Signature

*Jann Dean*  
Supervisory Certification

8/11/16  
Date

## TRACK INSPECTION REPORT

Name W. Bryant Date 08-10-16 Page 2 of 2  
(Please Print)  
Watchman \_\_\_\_\_ WO# 2515816  
Inspected From BWF To \_\_\_\_\_

[illegible]

Item	Comments
------	----------

[illegible]

Were switches in the area inspected? Yes ✓ No       

Is this a Special Inspection? Yes \_\_\_\_\_ No ✓

Reason for Special Inspection?

Walter W. B. Gunt  
Track Inspectors Signature

*James R. Riva*  
Supervisory Certification

8/11/16  
Date



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2514416 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

1)Track Inspection completed..No defects noted.

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/11/16
Target Finish:	8/11/16
Actual Start:	8/11/16
Actual Finish:	8/11/16
Report Date:	8/5/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48473

Job Plan:	2954
Job Desc:	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		



- Maximo

Maryland Department of Transportation

## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2514416 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

1)Track Inspection completed..No defects noted.

### Related Records

WO	Description	Class	Status	Relationship
3339545	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	CLOSE	FOLLOWUP

### Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	LEAD		WBRYAN							N	08:00	04:00	392.42
Total Actual Labor:													392.42



Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2514416 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

1)Track Inspection completed..No defects noted.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor



## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 3339545 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)

1)Track Inspection completed..No defects noted.

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
---------	-------------	-----------------	-------------------	--------------

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/22/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

### Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		





MD - Maximo

Maryland Department of Transportation

## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 3339545 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)

1)Track Inspection completed..No defects noted.

### Related Records

WO	Description	Class	Status	Relationship
2514416	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor